

Figure 19 – Side View, Optional Tether Anchorage Test for Passenger Cars until September 1, 2004