


TYPICAL SLIP-FIT ANGLE TYPE STUFFING BOX AND PACKING GLAND LEAD ENTRANCE

Plugs shall be secured by spot welding or brazing, weld may be on plug, clamp, or fastening bolt



TYPICAL PLUG FOR SPARE LEAD ENTRANCE HOLE

Figure 10